

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16			
A																A			
B	<p>Parameterliste</p> <p>A04 =65Hz B31 =0 F02 =8sec C11 = 0 A03 =60Hz B098 =1 F03 =5sec C12 = 0 A11 =5Hz C01 = no C13 = 1 A12 =65Hz C02 = no C14 = 0 A41 =1 c03 = 15 C15 = 0 A61 =65Hz C04 = no c 05 = no</p> <p>Reihenfolge beachten!!!</p>															B			
C																C			
D																D			
E																E			
F					Datum	14.11.2007											=		F
					Bearb.	Robak											+		
					Gepr.														
	Zustand	Änderung	Datum	Name	Norm		Urspr.	Ers. f.	Ers. d.	Schaltplan								Blatt <X>	
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16		von 1Bl.	

Parameterliste USA